




Run cable through connector

Crimp connector onto cable

Tighten Sealing Nut temporary







V1.0

